

City of Greater Geraldton Municipal Inventory of Heritage Places Place Record

Area: Geraldton Place Number: 12 Category: 3
Assessment Date: 15/10/1996 Last Revision Date: 06/07/2009
HCWA Number: 13203 Asset ID: MCH126921

PLACE DETAILS

Name: House

Other Names: 168 Augustus Street

Type of Place: House

Address: 168 Augustus Street

Suburb: Beachlands

LOCATION

 Map
 14.14
 GPS
 6814078.00
 GPS
 265955.000

 Reference:
 Northing:
 0000
 Easting:
 000



Photo Description: 20/12/2007 Rod Milne Face stonework to the side elevation.

Generated: 13/12/2018 Page 1 of 4

SITE DETAILS

Lot No.: Lot 1

Reserv No.: Assess No.: 20559

Dia/Plan: Vol/Fol:

USE OF PLACE

Original Use: Residence Current Use: Residence

Ownership:

Public Access: No Occupied: Occupied

DESCRIPTION

Walls: Stone/Brick Roof: Colorbond

Condition: Good Integrity:

Original fabric: Stone walls

Modifications: Face brick bay window rendered

Situated on a comer location, the main house has a hipped roof and a separate verandah roof to the front facade which is supported on timber verandah posts. The verandah features a simple decorative frieze and brackets to the posts. To the south west comer, a large multi hipped bay roof with wide eaves covers a rendered brick bay addition. The walls to the west and east feature coursed pointed stonework. The feature bay has three timber framed awning windows. A painted brick wall with piers and timber picket infill forms the street boundary.

HISTORY

Construction Date: 1930 Source: Shirley Scotter

Architect: Unknown Builder: Unknown

It is believed that this house was built in c 1930 for Mr Mc Kenzie Grant.

(Source: Shirley Scotter)

HISTORIC THEMES

HCWA: 104 Land allocation and subdivision

602 Early settlers

Generated: 13/12/2018 Page 2 of 4

STATEMENT OF SIGNIFICANCE

This house has a esthetic significance for its form and use of local stone. In addition the bay window is an unusual feature not commonly seen in

Generated: 13/12/2018



Photo Description: 15/10/1996 Suba & Grundy The bay window feature of the house was originally face brick.

Generated: 13/12/2018 Page 4 of 4