

# SITE DETAILS

Lot No.:	Lot 219		
Reserv No.:		Assess No.:	11583
Dia/Plan:		Vol/Fol:	

# USE OF PLACE

Original Use: Current Use:	Residence Residence		
Ownership:			
Public Access:	No	Occupied:	Occupied

### DESC RIPTION

Walls:	Rendered Masonry	Roof:	Asbestos
Condition:	Good	Integrity:	
Original fabric	:		
Modifications:	Verandahsremov	ed	

This prominently located two storey rendered masonry building has an					
asbestos gambrel roof punctuated by two tall corbelled brick chimneys to					
the north and north west. A£	n	s <sup>a</sup> Q	а	h ~ lq	

11

### HISTORIC THEMES

HCWA:104 Land allocation and subdivisionAHC:4.1.2 Making suburbs

### STATEMENT OF SIG NIFICANCE

Bendemeer has considerable aesthetic significance given its large scale




Photo Description: 15/10/1996 Suba & Grundy Front fence since replaced.