



City of Greater Geraldton
Municipal Inventory of Heritage Places
Place Record

Area: Geraldton	Place Number: 33	Category: 3
Assessment Date: 25/10/1996	Last Revision Date: 10/07/2009	
HCWA Number: 13225	Asset ID: MCH127000	

PLACE DETAILS

Name:	House
Other Names:	13 Burges Street
Type of Place:	House
Address:	13 Burges Street
Suburb:	West End

LOCATION

Map Reference:	14.15	GPS Northing:	6814103.00	GPS Easting:	265784.000
			0000		000



Photo Description:
31/10/2007
Rod Milne
Verandah features a decorative timber frieze.

SITE DETAILS

Lot No.:	Lot 3	Assess No.:	10603
Reserv No.:	Railway Reserve	Vol/Fol:	
Dia/Plan:			

USE OF PLACE

Original Use:	Residence	Occupied:	Occupied
Current Use:	Residence		
Ownership:			
Public Access:	No		

DESCRIPTION

Walls:	Weatherboard	Roof:	Comugated Iron
Condition:	Good	Integrity:	
Original fabric:	Weatherboard cladding		
Modifications:	Wall to property boundary		

This is a small timber framed weatherboard clad cottage with a comugated iron gable roof. There is a skillion roof to the rear with a rendered masonry chimney. To the front the separate hipped verandah roof is supported on timber posts with decorative timber braces and a valance below the verandah beam. The verandah features a timber criss-cross balustrade while the ends of the verandah are enclosed with weatherboard. Windows are timber framed and double hung with a central front entry door plus french window entry to the verandah. A brick and picket fence with a paling gate forms the street frontage of the property.

HISTORY

Construction Date:	unknown	Source:	Considine & Griffiths
Architect:	Unknown		
Builder:	Unknown		

No History Available.

HISTORIC THEMES

HCWA:	104 Land allocation and subdivision
-------	-------------------------------------

AHC:	202 Rail and light rail transport 605 Famous and infamous people 4.1.2 Making suburbs 3.8.6 Building and maintaining railways
------	--

STATEMENT OF SIGNIFICANCE

This house is a good example of a simple, timber clad residence of its era given its high integrity. Furthermore, the place contributes to the streetscape given its simple form, construction materials and decorative features including the timber valance and braces. The place has rarity

OTHER PHOTOS




Photo Description:
25/10/1996
Suba & Grundy
Front fence partly obscures view.