



City of Greater Geraldton
Municipal Inventory of Heritage Places
Place Record

| | | |
|-----------------------------|--------------------------------|-------------|
| Area: Geraldton | Place Number: 87 | Category: 3 |
| Assessment Date: 25/10/1996 | Last Revision Date: 27/10/2009 | |
| HCWA Number: 13342 | Asset ID: | MCH126499 |

PLACE DETAILS

| | |
|----------------|-------------------|
| Name: | House |
| Other Names: | 1 Crowther Street |
| Type of Place: | House |
| Address: | 1 Crowther Street |
| Suburb: | West End |

LOCATION

| | | | | | |
|----------------|-------|---------------|------------|--------------|------------|
| Map Reference: | 14.14 | GPS Northing: | 6814097.00 | GPS Easting: | 265555.000 |
| | | | 0000 | | 000 |



Photo Description:

13/04/2008

Tanya Henkel

Weatherboard cottage set behind picket fence.

SITE DETAILS

| | | | |
|-------------|-------|-------------|-------|
| Lot No.: | Lot 3 | Assess No.: | 10515 |
| Reserv No.: | | Vol/Fol: | |
| Dia/Plan: | | | |

USE OF PLACE

| | | | |
|----------------|-----------|-----------|----------|
| Original Use: | Residence | | |
| Current Use: | Residence | | |
| Ownership: | | | |
| Public Access: | No | Occupied: | Occupied |

DESCRIPTION

Walls: Weatherboard Roof: Comugated Iron
Condition: Good Integrity:
Original fabric:
Modifications: Verandah pitch, cladding and posts

This is a small timber framed weatherboard clad cottage with a galvanised iron gambrel roof with slatted gablets. The main roof extends to the rear as a broken back skillion roof. A weatherboard clad extension to the rear has a gable roof with a small skillion roof below the east gable end which merges to the skillion roof of the main building. To the front facade a separate shallow pitched shadowline clad verandah roof is supported on chamfered timber posts. Windows are timber framed and

AHC: 4.1.2 Making suburbs

STATEMENT OF SIGNIFICANCE

This simple house has considerable aesthetic appeal given that it has retained much of its original fabric including its weatherboard cladding, corbelled brick chimney and gambrel roof form. As such the place contributes to the built environment of the locale.

MANAGEMENT CATEGORY

Management Category: 3

Level of Significance:




Photo Description:

25/10/1996

Suba & Grundy

Unsympathetic asbestos fence and metal verandah poles since removed.