

### SITE DETAILS

Lot No.:	Lot 1020	Assess No.:	10307
Reserv No.:		Vol/Fol:	
Dia/Plan:			

### USE OF PLACE

Original Use:	Residence	Occupied:	Occupied
Current Use:	Residence		
Ownership:			
Public Access:	No		

### DESCRIPTION

Walls:	Brick (Rendered/ Painted)	Roof:	Tile
Condition:	Good	Integrity:	
Original fabric:			
Modifications:			

This rendered brick house has a tiled hipped roof with separate gables to the main front room and to the rear. The painted walls to the front have plain render to the lower two-thirds with stucco above, to the sides the lower two-thirds is painted brick with stucco above. The hipped roof extends to cover the front verandah which is supported on half decorative concrete posts set on masonry pillars with a masonry balustrade between them. The front gable end has a circular timber vent. Below the vent there are three windows to the main room above which is a tiled awning supported by timber braces. A tall chimney punctuates the tiled roof. Construction materials of the front fence, being large limestone blocks with pool fence infill panels, is not in keeping with the style of the house.

### HISTORY

Construction Date:	unknown	Source:	
Architect:	Unknown		
Builder:	Unknown		

No History Available.

## HISTORIC THEMES

HCWA:	104 Land allocation and subdivision
AHC:	4.1.2 Making suburbs

## STATEMENT OF SIGNIFICANCE

This house has retained much of its original fabric and style, including decorative elements to the verandah and gable end, which combine to streetscape.

RECOMMEND), wwwE9




Photo Description:

25/10/1996

Suba & Grundy

Front fence - limestone block pier wall with iron infill.