

City of Greater Geraldton Municipal Inventory of Heritage Places Place Record

Area:	Geraldton	Place N	Number:	99	Categ	ory:	3	
Assess	ment Date:	25/10/1996	Last Re	vision	Date:	28/1	0/2009	
HC WA	Number:	13352	Asset	D:		MCI	H126546	

PLACE DETAILS

Name: Other Names: Type of Place: Address:	House 10 Du Boulay Street House 10 Du Boulay Street
Address:	10 Du Boulay Street
Suburb:	West End

LOCATION

Мар	14.15	GPS	6814112.00	GPS	265647.000
Reference:		Northing:	0000	Easting:	000



Photo Description: 22/11/2007 Rod Milne View of front facade from Du Boulay Street.

SITE DETAILS

Lot No.:	Lot 1012		
Reserv No.:		Assess No.:	10299
Dia/Plan:		Vol/Fol:	

USE OF PLACE

Original Use: Current Use:	Residence Residence		
Ownership:			
Public Access:	No	Occupied:	Occupied

DESC RIPTION

Walls:	Brick (Painted)	Roof:	Corrugated Iron
Condition:	Good	Integrity:	
Original fabric:			
Modifications:	Brickextension		

This painted brick house has a corrugated iron gambrel roof which extends broken-back to cover the front verandah. The verandah is supported on timber posts which have timber c $Pq^{a} EQa$

STATEMENT OF SIG NIFIC ANCE

This small house has a esthetic appeal given that it has retained much of its original fabric and decorative detailing. The place makes a positive contribution to the streetscape of the area.

RECOMMENDATION: Property owners should be encouraged to retain and enhance the character houses located in Du Boulay Street which, together with the gardens and row of street trees, present as a special streetscape worthy of preservation.

MANAGEMENTCATEG ORY

Management Category:	3
Level of Significance:	MODERATE SIG NIFIC ANCE: Important to the
	heritage of the locality.
Management	Conservation of the place is recommended.
Recommendation:	Any proposed change to the place should not
	unduly impact on the heritage values of the
	place and should retain significant fabric
	wherever feasible.

OTHER LISTING S

No other listings

SUPPORTING INFORMATION



Photo Description: 25/10/1996 Suba & Grundy Verandah braces and casement windows a feature.