



City of Greater Geraldton
Municipal Inventory of Heritage Places
Place Record

| | | |
|-----------------------------|--------------------------------|-------------|
| Area: Geraldton | Place Number: 252 | Category: 3 |
| Assessment Date: 24/10/1996 | Last Revision Date: 27/11/2009 | |
| HCWA Number: 13422 | Asset ID: MCH126615 | |

PLACE DETAILS

| | |
|----------------|------------------|
| Name: | House |
| Other Names: | 1 Holland Street |
| Type of Place: | House |
| Address: | 1 Holland Street |
| Suburb: | Geraldton |

LOCATION

| | | | | | |
|----------------|-------|---------------|------------|--------------|------------|
| Map Reference: | 15.14 | GPS Northing: | 6814108.00 | GPS Easting: | 266623.000 |
| | | | 0000 | | 000 |



Photo Description:
29/10/2007
Rod Milne
View of house from Holland Street.

SITE DETAILS

| | | | |
|-------------|-------|-------------|-------|
| Lot No.: | Lot 1 | Assess No.: | 11209 |
| Reserv No.: | | Vol/Fol: | |
| Dia/Plan: | | | |

USE OF PLACE

| | | | |
|----------------|-----------|-----------|----------|
| Original Use: | Residence | | |
| Current Use: | Residence | | |
| Ownership: | | | |
| Public Access: | No | Occupied: | Occupied |

DESCRIPTION

| | | | |
|---|---------------------------------------|------------|----------------|
| Walls: | Weatherboard | Roof: | Comugated Iron |
| Condition: | Good | Integrity: | |
| Original fabric: | | | |
| Modifications: | Tall brick wall to property frontage. | | |
| <p>This timber framed weatherboard clad cottage has a hipped comugated iron roof with a lean-to roof to the rear and a separate gable roof to the front (main) room. The gable end has fibro infill. A separate verandah roof to the front facade is supported on turned timber posts with a decorative metalwork valance. Windows are a mixture of timber and aluminium frames with aluminium awnings to the front room and side. There is a brick chimney to the rear of the main roof and an attached carport to the side.</p> | | | |

HISTORY

| | | | |
|-----------------------|---------|---------|--|
| Construction Date: | unknown | Source: | |
| Architect: | Unknown | | |
| Builder: | Unknown | | |
| No History Available. | | | |

HISTORIC THEMES

| | |
|-------|-------------------------------------|
| HCWA: | 104 Land allocation and subdivision |
| AHC: | 4.1.2 Making suburbs |

STATEMENT OF SIGNIFICANCE

This house is representative of weatherboard clad houses of its style and era. It enhances the streetscape of the area.

MANAGEMENT CATEGORY

| | |
|----------------------------|---|
| Management Category: | 3 |
| Level of Significance: | MODERATE SIGNIFICANCE: Important to the heritage of the locality. |
| Management Recommendation: | Conservation of the place is recommended. Any proposed change to the place should not unduly impact on the heritage values of the place and should retain significant fabric wherever feasible. |

OTHER LISTINGS

No other listings

SUPPORTING INFORMATION

OTHER PHOTOS



Photo Description:
24/10/1996
Suba & Grundy
Metal veranda h supports since replaced.