

SITE DETAILS				
Lot No.: Reserv No.: Dia/Plan:	Lot 1	Assess No.: Vol/Fol:	10048	

# USE OF PLACE

Original Use: Current Use:	Residence Office		
Owne <i>r</i> ship:			
Public Access:	No	Occupied:	Occupied

### **DESCRIPTION**

	DIDO		
Walls: Condition: Original fabric Modifications:		Roof: Integrity:	Corrugated Iron
gambrel roof p decorative mo clad lean-to to window has be roof to the nor posts with mas the verandah double hung v	punctuated by two lan otifs below the corbelli o the rear. A new gab een added to the wes th and east facades is sonry piers below. A de posts. Some original w with a large set of alum sidence, the building h	ge corbelled cl ng. There is a ti le roof with fibre t side. A separa supported on l ecorative fretwo vindows are time ninium doors to	mberframed fibro o infill and a dormer ate bull nose verandah half tumed timber ork frieze runs between berframed and the east elevation.

	HIS	TORY	
Construction Date: Architect: Builder:	unknown Unknown Unknown	Source:	
No History Available.			

### HISTORIC THEMES

HC WA:	104 Land allocation and subdivision
	308 Commercial services and industries
AHC:	4.1.2 Making suburbs
	3.19 Marketing and retailing

# STATEMENT OF SIG NIFICANCE

Although the place has had some alterations undertaken, the place still contributes to the streetscape of the area given that some original built features are retained such as the bullnose verandah with its decorative elements to the verandah frieze and the corbelled chimneys.

### MANAGEMENTCATEG ORY

Management Category:	4
Level of Significance:	SOME SIG NIFICANCE: Contributes to the
	heritage and/or historical development of the
	locality.
Management	Conservation of the place is desirable. Any
Recommendation:	proposed change to the place should be in
	sympathy with the heritage values of the place.

### OTHER LISTING S

No other listings

## SUPPORTING INFORMATION

### OTHER PHOTOS




Photo Description: 5/12/1996 Suba & Grundy Picket fence and palm tree since removed.