



City of Greater Geraldton
Municipal Inventory of Heritage Places
Place Record

Area: Geraldton	Place Number: 152	Category: 3
Assessment Date: 15/10/1996	Last Revision Date: 04/11/2009	
HCWA Number: 13402	Asset ID: MC H126982	

PLACE DETAILS

Name:	House
Other Names:	113 Fitzgerald Street
Type of Place:	House
Address:	113 Fitzgerald Street
Suburb:	Geraldton

LOCATION

Map Reference:	14.14	GPS Northing:	6813892.00	GPS Easting:	266461.000
			0000		000



Photo Description:
6/12/2007
Rod Milne
Shingle roof a feature.

SITE DETAILS

Lot No.:	Lot 19	Assess No.:	11141
Reserv No.:		Vol/Fol:	
Dia/Plan:			

USE OF PLACE

Original Use:	Residence		
Current Use:	Residence		
Ownership:			
Public Access:	No	Occupied:	Occupied

DESCRIPTION

Walls: Limestone Roof: Shingle
Condition: Good Integrity:
Original fabric:
Modifications:

This stone house is hidden from the street behind a high brick wall and has

HISTORIC THEMES

HCWA:	104 Land allocation and subdivision 300 Occupations
AHC:	4.1.2 Making suburbs

STATEMENT OF SIGNIFICANCE

Although set behind a tall brick wall, the main and verandah roof form are still evident. The place adds to the streetscape of the area and is evidence of the use of local materials. The large scale of the residence is unusual for this locale.

MANAGEMENT CATEGORY

Management Category:	3
Level of Significance:	MODERATE SIGNIFICANCE: Important to the heritage of the locality.
Management Recommendation:	Conservation of the place is recommended. Any proposed change to the place should not unduly impact on the heritage values of the place and should retain significant fabric wherever feasible.

OTHER LISTINGS

No other listings

SUPPORTING INFORMATION

"Geraldton Guardian".
Feilman & Associates, "Survey of Places of Historic and Landscape Significance in Geraldton", 1977.

OTHER PHOTOS



Photo Description:
15/10/1996
Suba & Grundy
House hidden by high brick wall.