

City of Greater Geraldton Municipal Inventory of Heritage Places Place Record

Area: Geraldton	Place Num	nber:	58	Categ	ory:	3
Assessment Date:	05/12/1996	Last Re	vision	Date:	06/1	0/2009
HCWA Number:	13242	AssetI	D:		MCI	H126782

PLACE DETAILS

Name: Other Names:	House 124-126 Chapman Road
Type of Place:	House
Address:	124-126 Chapman Road
Suburb:	Geraldton

LOCATION

Мар	15.16	GPS	6815645.00	GPS	267277.000
Reference:		Northing:	0000	Easting:	000



Photo Description: 19/11/2007 Rod Milne Side view of the semi-detached cottages

SITE DETAILS				
Lot No.: Reserv No.: Dia/Plan:	Lot 3	Assess No.: Vol/Fol:	12644	

USE OF PLACE

Original Use: Current Use:	Residence Residence		
Ownership:			
Public Access:	No	Occupied:	Occupied

DESCRIPTION					
Walls:	Brick	Roof:	Corrugated Iron		
Condition:	Good	Integrity:			
Original fabric	:				
Modifications: Front verandahsenclosed with brick.					

These two semi detached cottages each have a hipped roof to the rear and a separate gable to the front. A central rendered parapet is located between the two hipped roofs. A separate verandah roof is located to the front of the cottages. The verandahs have brick infill and aluminium windows. The side windows are timber framed and double hung. There is a brick addition with a skillion roof to the rear. The property has a tall rendered brick wall with a timber picket gate to each cottage to the street facade.

HISTORY

Construction Date:	unknown	Source:
Architect:	Unknown	
Builder:	Unknown	

According to Shirley Scotter the Wardrops and the Nancarrows lived in these houses. Both worked for the governme se9 9 sQ

308 Commercial services and industriesAHC: 4.1.2 Making suburbs3.19 Marketing and retailing

STATEMENT OF SIG NIFIC ANCE

The duplex at 124-126 Chapman Road contributes to the streetscape given its good condition, simple style and small scale. Built elements such as the roof form, the gables to the street facade and the dividing parapet wall all combine to give the place aesthetic appeal.

MANAGEMENTCATEG ORY

Management Categor	<i>r</i> : 3	
Level of Significance:	MODERATE SIG NIFICANCE: Important to the	
	heritage of the locality.	
Management		
1 ® ybRVux h	•" †01 w v= • • @ `•` v2"› 'Ó " \$0	"\$" " à †\




Photo Description: 5/12/1996 Suba & Grundy View from Chapman Road.