



City of Greater Geraldton
Municipal Inventory of Heritage Places
Place Record

Area: Geraldton	Place Number: 202	Category: 4
Assessment Date: 24/10/1996	Last Revision Date: 24/11/2009	
HCWA Number: 13299	Asset ID: MC H126952	

PLACE DETAILS

Name:	House
Other Names:	93 Gertrude Street
Type of Place:	House
Address:	93 Gertrude Street
Suburb:	Geraldton

LOCATION

Map Reference:	15.14	GPS Northing:	6813387.00	GPS Easting:	267632.000
			0000		000



Photo Description:
14/11/2007
Rod Milne
Set above the street level

SITE DETAILS

Lot No.:	Lot 137	Assess No.:	16214
Reserv No.:		Vol/Fol:	
Dia/Plan:			

USE OF PLACE

Original Use:	Residence		
Current Use:	Residence		
Ownership:			
Public Access:	No	Occupied:	Occupied

DESCRIPTION

Walls: Weatherboard/Fibro Roof: Zincalume
Condition: Good Integrity:
Original fabric:
Modifications:

This timber framed house has a hipped zincalume roof with broken back extensions which cover the verandahs to the front (west) and north. To the rear there is a lean-to roof and to the south west a separate gable roof covers the main room. The house is clad with weatherboard to window sill height with fibro above and fibro and timber batten to the gable end. The front verandah is supported on timber posts with a timber balustrade between. The north verandah is enclosed with weatherboard below and windows above. The windows to the gable and south side have corrugated iron awnings. There is a small brick chimney to the north east and a carport with a lean-to roof is attached to the north side.

HISTORIC THEMES

HCWA:	104 Land allocation and subdivision 300 Occupations
AHC:	4.1.2 Making suburbs

STATEMENT OF SIGNIFICANCE

This house retains some of its original fabric. The place, set in a high position, contributes to the built environment of the area. It is evidence of the style of worker's cottage of its era.

MANAGEMENT CATEGORY

Management Category:	4
Level of Significance:	SOME SIGNIFICANCE: Contributes to the heritage and/or historical development of the locality.
Management Recommendation:	Conservation of the place is desirable. Any proposed change to the place should be in sympathy with the heritage values of the place.

OTHER LISTINGS

Shire of Greenough - Town Planning Scheme (69), 01/01/1970
National Trust of WA - Recorded, 01/01/1970

SUPPORTING INFORMATION

Bibliography:
Feilman, M., "Greenough Historical Survey of the Front Flats", 1977 (69).
Suba, T., "The Greenough Front Flats Bibliography of Local Sources and Table of Heritage Places", 1994.
HCWA Database No. 13994.

OTHER PHOTOS




Photo Description:
24/10/1996
Suba & Grundy
Asbestos roof since replaced.