

City of Greater Geraldton Municipal Inventory of Heritage Places Place Record

Area: Geraldton Place Number: 247 Category: 4
Assessment Date: 14/10/1996 Last Revision Date: 27/11/2009
HCWA Number: 13417 Asset ID: MCH126587

PLACE DETAILS

Name: House

Other Names: 132 Gregory Street

Type of Place: House

Address: 132 Gregory Street

Suburb: Beachlands

LOCATION

 Map
 14.14
 GPS
 6813628.00
 GPS
 266304.000

 Reference:
 Northing:
 0000
 Easting:
 000




Photo Description: 21/12/2007 Rod Milne Small weatherboard house.

Generated: 13/12/2018 Page 1 of 4

SITE DETAILS

Lot No.: Lot 22

Reserv No.: Assess No.: 11007

Dia/Plan: Vol/Fol:

USE OF PLACE

Original Use: Residence Current Use: Residence

Ownership:

Public Access: No Occupied: Occupied

DESCRIPTION

Walls: Weatherboard Roof: Comugated Iron

Condition: Good Integrity:

Original fabric:

Modifications: Much wall cladding replaced

This timber framed weatherboard clad house has a hipped corrugated iron roof which extends to cover the verandah to the front (east) elevation. The verandah is supported on chamfered timber posts and has a timber criss-cross balustrade. The windows are timber framed and double hung. There is an addition to the north facade. A brick chimney is sited to the rear of the main roof. The street boundary of the property has a Gothic picket fence.

HISTORY

Construction Date: 1925 Source: Owner

Architect: Unknown

Builder: Millers Timberco.

Mrs Ester G wynther lived here c 1929-30. This was her father's house. Ester was a nursing sister in Geraldton during the second world war. The house was owned by the Scott's from c 1930 until Mrs Scott died c 1960s.

(Source: Stan Gratte)

HISTORIC THEMES

HCWA: 104 Land allocation and subdivision

Generated: 13/12/2018 Page 2 of 4

AHC: 4.1.2 Making suburbs

STATEMENT OF SIGNIFICANCE

This house has a esthetic appeal given that much of its original fabric is intact, including the weatherboard cladding, brick chimney and symmetrical facade. The place, which is representative of houses of its era, contributes to the built environment of the locale.

MANAGEMENT CATEGORY

Management Category: 4

Level of Significance: SOME SIGNIFICANCE: Contributes to the

heritage and/or historical development of the

locality.

Management Conservation of the place is desirable. Any

Recommendation: proposed change to the place should be in

sympathy with the heritage values of the place.

OTHER LISTING S

No other listings

SUPPORTING INFORMATION

OTHER PHOTOS

Generated: 13/12/2018 Page 3 of 4




Photo Description: 14/10/1996 Suba & Grundy Prior to side addition.

Generated: 13/12/2018 Page 4 of 4